


Edsal Rivet Lock Record Storage Rack System

For use with standard 12" W x15" D x10" H record storage boxes - not included

v1.00



RR 31	318				
Dimensions: 4		44" W x	16 15/16	"Dx60"H	
Levels:		3			
Capacity:		18	Storage Boxes		
Parts Li	ist.		GOG NO.		
Ref	Description		Qty	Dimension	Part #
A	Beams		6	43"	6138
В	Braces		6	15 5/8"	7103
С	Separators		18	16"	9849
D	D Posts		4	60"	RLSU5TN

	. 00.0	7	7 00	
RR 41	324			
Dimensi	ions: 44" W x	16 15/16	" D x 84" H	
Levels:	4			
Capacity: 24		Storag	e Boxes	
Parts Lis	st:			
Ref	Description	Qty	Dimension	Part #
A	Beams	8	43"	6138
В	Braces	8	15 5/8"	7103
C	Separators	24	16"	9849
D	Posts	4	84"	RLSU7TN

Dimens	ions: 44"\	W x 32 7/8"	D x 60" H	
Levels:	3			
Capacit Parts Li	*	Storag	e Boxes	
Ref	Description	Qty	Dimension	Part #
A	Beams	6	43"	6138
В	Braces	6	32 1/8"	7104
C	Separators	18	32 1/2"	9848
	D Posts			

RR 42	348				
Dimensi	ions: 44" W	x 32 7/8"	D x 84" H		
Levels:	4				
Capacity Parts Lis	*	Storag	e Boxes		
Ref	Description	Qty	Dimension	Part#	
A	Beams	8	43"	6138	
В	Braces	8	32 1/8"	7104	
C	Separators	24	32 1/2"	9848	
D	Posts	4	84"	RLSU7TN	

General Instructions

Assembly is done with the rivet heads of Beams and Braces fitting into the key hole slots of the Posts. The tabs of the Separators fit into the rectangular slots on the top of the Beams to support the storage boxes. A rubber mallet may be used on the beams and braces to seat the rivets properly. A hammer can also be used, providing one uses a cloth or block of wood between the hammer head and the parts to prevent damage.

Safety Instructions

These units should be placed on a level surface. Failure to do so can result in poor performance or create a possible safety hazard. This unit should be securely anchored to a wall or floor with suitable fasteners, which are not included. Do not use this product for anything other than the manufacturers intended purpose. Do not stand on any part of the unit, or use it as a ladder. Do not overload. Evenly distribute the weight on each level and always keep the heavier loads near the bottom. Make certain that all the record storage cartons are properly centered on the separators. Use care when working with metal parts.

